

DEBBY RANSOM, R.N., R.H.I.T - Chief BUREAU OF FACILITY STANDARDS 3232 Elder Street P.O. Box 83720 Boise, Idaho 83720-0036 PHONE: (208) 334-6626

FAX: (208) 364-1888 E-mail: fsb@dhw.idaho.gov

June 23, 2010

RICHARD M. ARMSTRONG - Director

FerrenWeeks, Administrator Yellowstone Group Home #3 Hoopes 560 West Sunnyside Idaho Falls, Idaho 83401

RE: Yellowstone Group Home #3 Hoopes, Provider #13G065

Dear Mr. Weeks:

This is to advise you of the findings of the Medicaid/Licensure Fire Life Safety Survey, which was concluded at Yellowstone Group Home #3 Hoopes, on June 15, 2010.

Enclosed is a Statement of Deficiencies/Plan of Correction, Form CMS-2567, listing Medicaid deficiencies and a similar form listing State licensure deficiencies. In the spaces provided on the right side of each sheet, please provide a Plan of Correction. It is important that your Plan of Correction address each deficiency in the following manner:

- 1. What corrective action(s) will be accomplished for those individuals found to have been affected by the deficient practice;
- 2. How you will identify other individuals having the potential to be affected by the same deficient practice and what corrective action(s) will be taken;
- 3. What measures will be put in place or what systemic change you will make to ensure that the deficient practice does not recur;
- 4. How the corrective action(s) will be monitored to ensure the deficient practice will not recur, i.e., what quality assurance program will be put into place; and,
- 5. Include dates when corrective action will be completed. 42 CFR 488.28 states ordinarily a provider is expected to take the steps needed to achieve compliance

FerrenWeeks, Administrator June 23, 2010 Page 2 of 2

within 60 days of being notified of the deficiencies. Please keep this in mind when preparing your plan of correction. For corrective actions which require construction, competitive bidding, or other issues beyond the control of the facility, additional time may be granted.

Sign and date the form(s) in the space provided at the bottom of the first page.

After you have completed your Plan of Correction, return the original to this office by **July 6, 2010**, and keep a copy for your records.

Thank you for the courtesies extended to us during our visit. If you have any questions, please call or write this office at (208) 334-6626.

Sincerely,

TAYLOR BARKLEY

Health Facility Surveyor

Jay L Bory

Fire Life Safety & Construction Program

TB/lj

Enclosure

Printed: 06/22/2010 FORM APPROVED

p.11

DEPART	MENT OF HEALTH	AND HUMAN SERV & MEDICAID SERV	ICES					APPROVED . 0938-0391
STATEMENT OF DEFICIENCIES (X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:			(X2) MULTIPLE CONSTRUCTION (X A. BUILDING 02			(X3) DATE SURVEY COMPLETED		
13G065		B. WING0		06/14	06/15/2010			
NAME OF P	ROVIDER OR SUPPLIER		STREET ADD	RESS, CITY, ST	ATE, ZIP CODE	,		
YELLOW	STONE GROUP H	OME #3 (HOOPES)	•	OOPES FALLS, ID	92404			ļ
						R'S PLAN OF CORRE	CTION	(X5)
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENCII Y MUST BE PRECEEDED B LSC IDENTIFYING INFORM	YFULL	PREFIX TAG	(EACH COR	RECTIVE ACTION SHE RENCED TO THE APP DEFICIENCY)	QULD BE	(X5) COMPLETION DATE
K 000	INITIAL COMMENT	TS		K 000				
	construction. It is a with Quick Respon- complete fire alarm	gle story ,type V(000) a fully sprinklered 13- se sprinkler heads at l/smoke detection sy t on April 10, 1998 at or 6 ICF/MR beds.	D system ind has a stem.	j	Please Ian	- see	attach	
The following deficiencies were cited at the above facility during the annual Fire/Life Safety survey conducted on June 15, 2010. The facility was surveyed under the LIFE SAFETY CODE, 2000 Edition, Chapter 33, Existing Residential Board and Care Occupancies, adopted 11 March, 2003. In accordance with 42 CFR 483.470.								
	The annual fire/life by:	safety survey was co	onducted	į				
	Taylor Barkley Health Facility Surv Facility Fire Safety	reyor and Construction						
K0046	483.470(j)(1)(i) LIF STANDARD	E SAFETY CODE		K0046				
	Utilities comply with 33.2.5.1	Section 9.1. 32.2	.5.1,	÷				
	Based on observat facility failed to ens Section 9.1. The fa clients on the day o	-	that the blied with f six					
LABORATO	1	IDER/SUPPLIER REPRESI	, ,	NATURE 7	· J	TLE /	. 1 +	(X6) DATE
		men J. u		Ke	gionas.	unmine	uni	2/1/1/2
other safeg	uards provide sufficient p	th an asterisk (*) denotes protection to the patients. For not a plan of correction nents are made available	(See instruction n is provided. I	ns.) Except fo For nursing ho	r nursing homes, I mes, the above fir	the findings stated a ndings and plans of	bove are disclor correction are d	sable 90 days isclosable 14

program participation.

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 06/22/2010 FORM APPROVED OMB NO. 0938-0391

AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIE AND PLAN OF CORRECTION IDENTIFICATION NU			A. BUILDING	E 02		(X3) DATE SURVEY COMPLETED	
13G065			B. WING			06/15/2010	
YELLOWSTONE GROUP HOME #3 (HOOPES) 1949 H			DRESS, CITY, S IOOPES FALLS, ID				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENCII / MUST BE PRECEEDED B LSC IDENTIFYING INFORM	Y FULL	ID PREFIX TAG	PROVIDER'S PLAN ((EACH CORRECTIVE A CROSS-REFERENCED TO DÉFICIE	CTION SHOULD BE O THE APPROPRIATE	(X5) COMPLETION DATE
K0046	Continued From pa	age 1	!	K0046			
	Findings include;		İ	•			
	10:41 AM, observat multiple electrical ac noted by the Survey Maintenance Mana	tour on June 15, 20 tion of the garage revidence. Finding dapter in use. Finding for and the Facility ger. This deficiency a present on the day o	vealed a ngs were affected				
	10:47 AM, observat an extension cord the powerstrip behind the noted by the Survey Maintenance Manage	tour on June 15, 20 ion of the living room nat was plugged into ne television. Finding for and the Facility ger. This deficiency a present on the day of	revealed a s were affected				:
		ard I equipment shall be PA 70, Natíonal Elec					
	flexible cords and ca following: 1. As a substitute fo structure 2. Where run throug ceilings suspended of floors	rmitted permitted in Section 4 ables shall not be use r the fixed wiring of a th holes in walls, stru ceilings, dropped cei th doorways, window	ed for the a ctural lings, or				

2085220224

Yellowstone Group Homes

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

Printed: 06/22/2010 FORM APPROVED OMB NO. 0938-0391

STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION		(X1) PROVIDER/SUPPLIER/CLIA IDENTIFICATION NUMBER:		(X2) MULTII A. BUILDING	PLE CONSTRUCTION G 02		X3) DATE SURVEY COMPLETED	
13G065			B. WING		06/	15/2010		
	ROVIDER OR SUPPLIER VSTONE GROUP H	OME #3 (HOOPES)	1949 H	ORESS. CITY, S OOPES FALLS, ID	STATE, ZIP CODE			
(X4) ID PREFIX TAG	(EACH DEFICIENCY	ATEMENT OF DEFICIENCIE Y MUST BE PRECEEDED B LSC IOENTIFYING INFORM	YFULL	ID PREFIX TAG	PROVIDER'S PLAN OF C (EACH CORRECTIVE ACTIC CROSS-REFERENCED TO TH DEFICIENCY	ON SHOULD BE BE APPROPRIATE	(X5) COMPLETION DATE	
K0046	Exception: Flexible permitted to be atta accordance with the 5. Where concealer structural ceilings, seeilings, or floors	cord and cable shall ached to building surf e provisions of Section d behind building wall suspended ceilings, on n raceways, except a	aces in on 364-8. lls, dropped	K0048				
K0154	out of service for meriod, the authority notified, and the buil approved fire watch parties left unproted sprinkler system has 9.7.6.1 This Standard is not Based on record retained the facility did not has facility in the event of the facility had a coof the survey. The findings include During record review plans on June 15, 2 determined that the watch policy in the facility in the facility in the facility had a coof the survey.	utomatic sprinkler sy ore than 4 hours in a having jurisdiction solding shall be evacual system be provided sted by the shutdown is been returned to sold met as evidenced by the second steel of met as evidenced by the second steel in the second s	24-hour hall be ated or an for all until the ervice. by: ed that by for the failure. In the day argency was a fire noted by the failure.	K0154				

Printed: 06/22/2010

DEPARTMENT OF HEALTH AND HUMAN SERVICES CENTERS FOR MEDICARE & MEDICAID SERVICES

FORM APPROVED OMB NO. 0938-0391

p.14

		IDENTIFICATION NUMBER:		A. BUILDING 02		COMPLETED 06/15/2010	
13G065			B. WING	····	D6/		
	PROVIDER OR SUPPLIER VSTONE GROUP HO	OME #3 (HOOPES) 1949	ADDRESS, CITY, S HOOPES HO FALLS, ID				
(X4) ID PREFIX TAG	! (EACH DEFICIENCY	ATEMENT OF DEFICIENCIES Y MUST BE PRECEEDED BY FULL LSC IDENTIFYING INFORMATION)	ID PREFIX TAG	PROVIDER'S PLAN OF CO (EACH CORRECTIVE ACTIO CROSS-REFERENCED TO THI DEFICIENCY)	N SHOULD BE E APPROPRIATE	(X5) COMPLETION DATE	
K0154	Continued From pa	age 3	K0154				
K0155	service for more that the authority having and the building sha approved fire watch shall be proviunprotected by the system has been read that the facility did not have facility in the event of the facility had a certain of the survey. The findings include During record review plans on June 15, 2 determined that the watch policy in the fithe Surveyor and the	re alarm system is out of an 4 hours in a 24-hour period jurisdiction shall be notified, all be evacuated or an ided for all parties left shutdown until the fire alarm sturned to service. 9.6.1.8 ot met as evidenced by: view it was determined that ave a fire watch policy for the of a fire alarm system failure, ensus of six clients on the day of the facility's emergency 010 at 10:45 AM, it was facility did not have a fire accility. Findings were noted by e Facility Maintenance siency affected all staff and					

p.15

PRINTED: 06/22/2010 FORM APPROVED Bureau of Facility Standards STATEMENT OF DESICIENCIES (X1) PROVIDER/SUPPLIER/CLIA (X2) MULTIPLE CONSTRUCTION (X3) DATE SURVEY AND PLAN OF CORRECTION IDENTIFICATION NUMBER: COMPLETED A. BUILDING B. WING 13G065 06/15/2010 NAME OF PROVIDER OR SUPPLIER STREET ADDRESS, CITY. STATE, ZIP CODE **1949 HOOPES** YELLOWSTONE GROUP HOME #3 (HOOPES) IDAHO FALLS, ID 83404 PROVIDER'S PLAN OF CORRECTION SUMMARY STATEMENT OF DEFICIENCIES 1D (X5) COMPLETE (X4) 10(EACH DEFICIENCY MUST BE PRECEDED BY FULL PREFIX (EACH CORRECTIVE ACTION SHOULD BE PRÉFIX REGULATORY OR LSC IDENTIFYING INFORMATION) CROSS-REFERENCED TO THE APPROPRIATE DATE TAG TAG DEFICIENCY) M 000 16.03.11 Inital Comments M 000 The facility is a single story ,type V(000) construction. It is a fully sprinklered 13-D system with Quick Response sprinkler heads and has a complete fire alarm/smoke detection system. The home was built on April 10, 1998 and currently licensed for 6 ICF/MR beds. The following deficiencies were cited at the above facility during the annual Fire/Life Safety survey conducted on June 15, 2010. The facility was surveyed under the LIFE SAFETY CODE. 1976 Edition, " Lodging and Rooming Houses " contained in Chapter 11, " Lodging and Rooming House Occupancies " and applicable provisions of Chapters 01 through 07, Chapter 17 and Appendices A and B of the Life Safety Code, Impractical Evacuation Capability in accordance with IDAPA 16,03,11. The annual fire/life safety survey was conducted Taylor Barkley Health Facility Surveyor Facility Fire Safety and Construction

MM309 16.03.11.110 Fire and Life Safety Standards

Yellowstone Group Homes

MM309

Buildings on the premises used as facilities must meet all the requirements of local, state and national codes concerning fire and life safety standards that are applicable to ICF/MR facilities. This Rule is not met as evidenced by: Refer to federal deficiencies listed on the CMS

2567 form. K0154 Fire watch policy for sprinkler system

LABORATORY DIRECTOR'S OR PROVIDER/SUPPMER REPRESENTATIVE'S SIGNATURE

failure.

(X6) DATE

STATE FORM

administrator

If continuation sheet 1 of 2

PRINTED: 06/22/2010 FORM APPROVED

Bureau o	of Facility Standards				***************************************		
STATEMENT OF DEFICIENCIES AND PLAN OF CORRECTION (X1) PROVIDER/SUPPLIDENTIFICATION N 13G06		MBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 02 B. WING		COMPL	(X3) DATE SURVEY COMPLETED 06/15/2010 .	
NAME OF P	ROVIDER OR SUPPLIER			DRESS, CITY.	STATE, ZIP CODE		
	STONE GROUP HOM	E #3 (HOOPES)	1949 HOC				
(X4) ID PREFIX TAG	(EACH DEFICIENCY	TEMENT OF DEFICIENCIE MUST BE PRECEDED BY SC IDENTIFYING INFORM	FULL	ID PREFIX TAG	PROVIDER'S PLAN OF (EACH CORRECTIVE ACT CROSS-REFERENCED TO T DEFICIENC	TON SHOULD BE THE APPROPRIATE	(X5) COMPLETE DATE
MM309	Continued From Pa	age 1	i	MM309			
į	2. K0155 Fire watch failure.	h policy for fire alarm	system				
	3. K046 Multiple ele cord.	ectrical adapter and e	extension	ļ			
į							! .
i 				ļ			
							İ
			İ				İ
				i			[
			Ì				
			!	į			
TATE FORM	A	AND THE PROPERTY OF THE PROPER	D21100		E6KN21	If continue	tion sheet 2 of 2

p.4

Fire Life Safety Plan of Correction Home #3 Hoopes #13G065) constant \$1 w

K0046

The multiple wiring adapter has been removed. To assure that this deficiency doesn't reoccur a policy will be written regarding multiple adapters and extension cords. Responsible party is Ferren Weeks, Regional Administrator and will be completed by 7/10/2010. All staff will be in serviced on the policy and a copy will be placed in each homes Work Safety Manual. All staff will also be in serviced on the Work Safety Manual, its location in each home, and added to our Employee Orientation Packet. Checking for improper use of these items will be added to the daily night shift cleaning/responsibilities log.

Responsible person will be each Home Administrator to be completed by July 30th 2010

K0154

A fire watch policy has been developed and implemented in the event either system. becomes inoperable as stated in life safety standards K0154 and K0155. Responsible party is Ferren Weeks, Regional Administrator and will be completed by 7/10/2010.

Currently when either system is in trouble or there is false alarm the maintenance person is to be notified immediately and if the maintenance person is unreachable then the Regional Administrator will be contacted. The maintenance person is to then:

- Notify the Regional Administrator. (If maintenance person is unavailable the Regional Administrator will designate an employee to:)
- 2. Go to the location or direct the home staff how to correct the problem.
- 3. If unable to correct, our contract services will be contacted to correct the problem.
- 4. If unable to correct with in 4 hours then the fire watch policy will be implemented.

A copy of the Fire Watch Policies and Procedures will be provided to the Bureau. All staff will be in serviced on the policy and a copy will be placed in each homes Work Safety Manual. All staff will also be in serviced on the Work Safety Manual, its location in each home, and added to our Employee Orientation Packet.

Responsible person will be each Home Administrator to be completed by July 30th 2010.

K0155- Please refer to K0154

MM309(1 & 2) Please refer to K0154

MM309 (#3) Please refer to K0046

Arran Julados Reg- admin